

## Jeep Aluminum TrailChaser® Bumper Kits & Components

Location / Make / Model	Years	Kit#	Center#	Corner#	Corner Lights	Guard#	Guard Style	Fender Flare#	Footnotes
<b>Front Aluminum Bumpers</b>									
Jeep Gladiator JT	20 - 25	2082075	2081004	2081205	Included	--	--	--	--
		2082094	2081004	2081205	Included	2081255	Round	--	--
		2082095	2081004	2081205	Included	2081101	Angular	--	--
		2082074	2081004	2081207	Not compatible	--	--	--	--
		2082092	2081004	2081207	Not compatible	2081255	Round	--	--
		2082093	2081004	2081207	Not compatible	2081101	Angular	--	--
Jeep Wrangler JL	18 - 25	2082076	2081004	2081209	Accepts OE turn signal lamps	--	--	--	--
		2082098	2081004	2081209	Accepts OE turn signal lamps	2081255	Round	--	--
		2082099	2081004	2081209	Accepts OE turn signal lamps	2081101	Angular	--	--
		2082077	2081004	2081209	Accepts OE turn signal lamps	--	--	1500203	1
		2082096	2081004	2081209	Accepts OE turn signal lamps	2081255	Round	1500203	1
		2082097	2081004	2081209	Accepts OE turn signal lamps	2081101	Angular	1500203	1
		2082075	2081004	2081205	Included	--	--	--	--
		2082094	2081004	2081205	Included	2081255	Round	--	--
		2082095	2081004	2081205	Included	2081101	Angular	--	--
		2082074	2081004	2081207	Not compatible	--	--	--	--
		2082092	2081004	2081207	Not compatible	2081255	Round	--	--
		2082093	2081004	2081207	Not compatible	2081101	Angular	--	--
		Jeep Wrangler JK	07 - 18	2082046	2081001	2081205	Included	2081101	Angular
2082058	2081001			2081205	Included	2081255	Round	--	--
2082044	2081001			2081205	Included	--	--	--	--
2082055	2081001			2081207	Not compatible	2081101	Angular	--	--
2082054	2081001			2081207	Not compatible	2081255	Round	--	--
2082052	2081001			2081207	Not compatible	--	--	--	--
<b>Rear Aluminum Bumpers</b>									
Wrangler JL	18 - 25	2082082	2081025	2081221	Not included	--	--	--	--
		2082083	2081025	2081223	Included	--	--	--	--
Wrangler JK	07 - 18	2082036	2081021	2081221	Not included	--	--	--	--
		2082061	2081021	2081223	Included	--	--	--	--

### Footnotes

1 - OE turn signal lamps must be relocated to the new bumper corners #2081209